

Service Address	Current Object Code Line Material	Class of Object Code Material Classification	Object Code Material	Use Object Side	Current Property Side	Class of Property Code Material Classification	Property Code Field Material
600 S Hustis St	Iron	Previous Evaluation	Yes	No	Iron	Installation Record	Yes
845 Lake St	Iron	Previous Evaluation	Yes	No	Iron	Installation Record	Yes
443 E Griffith St	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
444 W Griffith	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
Beerstd	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
717 Lakeview Road	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
727 Lakeview Rd	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
450s lake st	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
500 W Juneau	Plastic	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
480 w Juneau	Plastic	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
255 s ridge	Plastic	Previous Evaluation	Yes	No	Plastic	Previous Evaluation	Yes
100 N Ann	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
280 N Ridge St	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
419 W Griffith	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
253 Ridge	Plastic	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
725 Industrial Ln	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
761 Industrial Lane	Iron	Previous Evaluation	Yes	No	Iron	Previous Evaluation	Yes
331 Riverview Dr	Iron	Previous Evaluation	Yes	No	Iron	Previous Evaluation	Yes
331 Riverview Dr	Iron	Previous Evaluation	Yes	No	Iron	Previous Evaluation	Yes
316 Tweedy St	Copper	Previous Evaluation	Yes	No	Plastic	Previous Evaluation	Yes
102N Lake St	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
400 W Juneau	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
737 E Lakeview Rd	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
266 S Lake St	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
4380 Lakeview	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
200 S Lake St	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
106 S Lake St	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
141 S Lake St	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
470 Rubicon St	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
470 Rubicon St	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
434 E Rubicon St	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
424 E Rubicon St	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
434 E Rubicon	Plastic	Previous Evaluation	Yes	No	Plastic	SL Repair/Replace Record	Yes
633 w Juneau st	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
326 w Juneau st	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
499 e rubicon st	Plastic	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
147 n lake st	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
118 n lake st	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
96 s lake st	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
500 E State rd 60	Plastic	Previous Evaluation	Yes	No	Plastic	Previous Evaluation	Yes
439 E Rubicon St	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
101 N Lake St	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
232 S Lake St	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
469 E Rubicon St	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
787 Circle Drive	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
511 Island View Circle	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
120 W Anthony	Plastic	Installation Record	Yes	No	Copper	Previous Evaluation	Yes
146 n lake st upper	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
146 n lake st lower	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
331 S Wales St	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
485 w Griffith	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
485 w Griffith	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
485 w Griffith	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
485 w Griffith st	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
485 w Griffith st	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
485 W Griffith Street 3	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
485 w Griffith st 8	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
485 w Griffith st apt7	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
485 w Griffith st house	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
505 W Griffith St 2	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
505 W Griffith st 1	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
505 W Griffith St 7	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
505 W Griffith st 8	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
505 W Griffith St	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
505 W Griffith St 4	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
505 W Griffith St 6	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
505 W Griffith St 5	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
480 W Griffith St 201	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
480 W Griffith St 203	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
480 W Griffith St 204	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
480 W GRIFFITH ST 101	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
480 W GRIFFITH ST 104	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes

480 W GRIFFITH ST 102	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
480 W GRIFFITH ST 103	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
480 W GRIFFITH ST 202	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
209 BIRCH ST	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
705 SPRUCE ST	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
106 N LAKE ST 8	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
796 SPRUCE ST	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
500 W GRIFFITH ST 203	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
500 W GRIFFITH ST 103	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
500 W GRIFFITH ST 104	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
500 W GRIFFITH ST 204	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
500 W GRIFFITH ST 201	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
500 W GRIFFITH ST 101	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
500 W GRIFFITH ST 102	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
500 W GRIFFITH ST 202	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
00 W GRIFFITH ST SPRIN	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
103 S RIDGE ST 1	Iron	Previous Evaluation	Yes	No	Iron	SL Repair/Replace Record	Yes
103 S RIDGE ST 2	Iron	Previous Evaluation	Yes	No	Iron	Previous Evaluation	Yes
103 S RIDGE ST 3	Iron	Previous Evaluation	Yes	No	Iron	SL Repair/Replace Record	Yes
103 S RIDGE ST 4	Iron	Previous Evaluation	Yes	No	Iron	SL Repair/Replace Record	Yes
103 S RIDGE 5	Iron	Previous Evaluation	Yes	No	Iron	SL Repair/Replace Record	Yes
103 S RIDGE ST 6	Iron	Previous Evaluation	Yes	No	Iron	SL Repair/Replace Record	Yes
208 LAKEVIEW RD	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
400 SANDY LN	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
265 S RIDGE ST	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
252 S LAKE ST	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
302 S OAKWOOD BLVD	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
609 W JUNEAU ST	Copper	Previous Evaluation	Yes	No	Copper	Installation Record	Yes
227 S WALES ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
700 INDUSTRIAL DR	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
351 S LAKE ST	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
125 E RUBICON ST	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
130 S HIGHLAND ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
132 S HIGHLAND ST	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
129 N LAKE ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
311 E TWEEDY ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
236 S MILL ST HOUSE	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
302 W JUNEAU ST	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
39 ISLAND VIEW CIRCLE	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
332 south lake street	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
101 S LAKE ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
116 E TWEEDY ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
236 E RUBICON ST	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
250 S ANN ST	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
217 S Ann St.	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
185 S OAKWOOD BLVD	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
215 S WALES ST	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
249 S WALES ST	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
213 W Griffith St	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
262 s hustis st	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
127 S HIGHLAND ST	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
124 S LAKE ST	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
247 S WALES ST	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
606 S LAKE ST NORTH	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
606 S LAKE ST SOUTH	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
240 S Hustis St.	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
452 Sandy Lane	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
318 S HUSTIS ST	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
750 INDUSTRIAL DR	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
472 SANDY LN EAST	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
684 SPRUCE ST	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
349 HUSTIS ST	Plastic	Previous Evaluation	Yes	No	Plastic	Installation Record	Yes
130 S HUSTIS ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
231 N Ridge St.	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
453 Sandy Lane West	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
612 W Juneau St	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
441 Sandy Lane	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
451 Sandy Lane East	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
233 S LAKE ST	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
141 N HIGHLAND ST	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
453 E RUBICON ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
339 S MILL ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
277 N RIDGE ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes

150 S LAKE ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
760 S Lake St	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
113 S Oakwood BLVD	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
313 W JUNEAU ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
131 S LAKE ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
133 S LAKE ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
135 S LAKE ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
138 S LAKE ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
116 E GRIFFITH ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
252 S HUSTIS ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
131 W TWEEDY ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
129 W TWEEDY ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
286 N lake St. Upper	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
284 N Lake St.	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
448 W Griffith St	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
211 Oakwood BLVD	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
415 E Rubicon St	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
417 E Rubicon St	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
244 n lake st	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
235 s Ann st	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
226 s ann st	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
425 e rubicon st	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
113 s lake st	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
303 w Juneau st	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
226 e Anthony st	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
128 e Anthony st	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
120 highland st	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
127 e Anthony st	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
327 e Anthony st	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
200 e Anthony st	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
768 s lake st	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
112 w tweedy st	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
407 E RUBICON ST	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
425 E TWEEDY ST	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
319 e Anthony st	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
240 -242 S ANN ST	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
178 S OAKWOOD BLVD	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
85 ISLAND VIEW CIRCLE	Plastic	Installation Record	Yes	No	Plastic	Installation Record	Yes
240 s maple st	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
921 Lakeview rd	Copper	Previous Evaluation	Yes	No	Plastic	SL Repair/Replace Record	Yes
560 island view cr	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
563 island view circle	Copper	Previous Evaluation	Yes	No	Plastic	SL Repair/Replace Record	Yes
571 island view circle	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
268 n lake st	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
917 LAKEVIEW RD	Plastic	Previous Evaluation	Yes	No	Plastic	SL Repair/Replace Record	Yes
252 S WALES ST	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
254 S WALES ST	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
168 LAKEVIEW RD	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
N4298 Daley rd	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
227 S ANN ST	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
125 E GRIFFITH ST	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
531 island view	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
577 island view	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
579 island view	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
519 island view	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
404 S LAKE ST HOUSE	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
40 ISLAND VIEW CIRCLE	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
30 ISLAND VIEW CIRCLE	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
67 ISLAND VIEW CIRCLE	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
818 CIRCLE DR	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
551 island view	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
337 S WALES ST	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
752 S LAKE ST	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
428 w griffith st	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
547 island view	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
299 S OAKWOOD BLVD	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
432 W JUNEAU ST	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
244 S RIDGE ST	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
132 N HUSTIS ST UPPER	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
130 N HUSTIS ST LOWER	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
43 ISLAND VIEW CIRCLE	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
234 S OAKWOOD BLVD	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
225 S OAKWOOD BLVD	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes

220 W GRIFFITH ST EAST	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
224 W GRIFFITH ST WEST	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
281 S OAKWOOD BLVD	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
170 S OAKWOOD BLVD	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
274 S OAKWOOD BLVD	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
143 S OAKWOOD BLVD	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
244 S OAKWOOD BLVD	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
190 Oakwood blvd	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
263 hustis	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
264 Maple	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
262 S MAPLE ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
213 E ANTHONY ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
304 S HUSTIS ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
284 S OAKWOOD BLVD	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
243 S ANN ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
265 S OAKWOOD BLVD	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
199 S OAKWOOD BLVD	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
109 W TWEEDY ST	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
301 E TWEEDY ST	Copper	Previous Evaluation	Yes	No	Copper	Water Sampling Only	Yes
337 W TWEEDY ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
117 E TWEEDY ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
421 SANDY LN	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
331 E TWEEDY ST	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
726 SPRUCE ST	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
537 W JUNEAU ST C	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
699 SPRUCE ST	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
305 W TWEEDY ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
322 W TWEEDY ST	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
710 SPRUCE ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
281 N LAKE ST	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
269 N LAKE ST	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
537 W JUNEAU ST A	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
420 SANDY LN	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
220 S RIDGE ST	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
119 S HIGHLAND ST	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
145 S HIGHLAND ST	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
116 S RIDGE ST	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
431 SANDY LN	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
121 N RIDGE ST	Plastic	Installation Record	Yes	No	Copper	SL Repair/Replace Record	Yes
228 N HIGHLAND ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
121 W TWEEDY ST	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
295 N RIDGE ST	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
300 N RIDGE ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
119 S RIDGE ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
143 N RIDGE ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
285 N RIDGE ST	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
125 N HIGHLAND ST	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
322 S MILL ST	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
124 S RIDGE ST	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
211 N HIGHLAND ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
213 N HIGHLAND ST	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
330 S ANN ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
141 S RIDGE ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
112 S LAKE ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
127 S LAKE ST B	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
127 S LAKE ST A	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
127 S LAKE ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
537 W JUNEAU ST E	Plastic	Previous Evaluation	Yes	No	Plastic	Previous Evaluation	Yes
305 e Griffith	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
247 N RIDGE ST	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
144 S RIDGE ST	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
124 highland st	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
238 S WALES ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
27 W JUNEAU ST UPPER	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
27 W JUNEAU ST Lower	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
205 W JUNEAU ST	Plastic	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
405 W JUNEAU ST	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
335 W JUNEAU ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
227 W GRIFFITH ST	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
446 W JUNEAU ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
537 W JUNEAU ST G	Plastic	Previous Evaluation	Yes	No	Plastic	Previous Evaluation	Yes
507 W JUNEAU ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
328 S HUSTIS ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes

729 W JUNEAU ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
720 W JUNEAU ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
497 W JUNEAU ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
320 W GRIFFITH ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
136 N LAKE ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
111 N LAKE ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
109 N LAKE ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
260 N LAKE ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
312 W JUNEAU ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
410 E GRIFFITH ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
217 S LAKE ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
537 w Juneau st b	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
119 S LAKE ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
324 S WALES ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
713 W JUNEAU ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
247 S LAKE ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
212 W GRIFFITH ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
225 S LAKE ST LOWER	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
227 S LAKE ST UPPER	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
292 N LAKE ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
138 LAKEVIEW RD	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
438 W GRIFFITH ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
128 N LAKE ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
126 N LAKE ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
235 N LAKE ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
312 S WALES ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
325 W JUNEAU ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
276 N LAKE ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
315 S HUSTIS ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
171 S OAKWOOD BLVD	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
485 W JUNEAU ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
244 S LAKE ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
147 S LAKE ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
133 N LAKE ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
729 SPRUCE ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
304 S LAKE ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
W4436 e Lakeview rd	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
451 w Juneau st	Copper	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
308 E RUBICON ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
235 S HUSTIS ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
313 S LAKE ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
303 S LAKE ST UNIT #2	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
303 S LAKE ST UNIT #1	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
324 E RUBICON ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
242 S MAPLE ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
325 S MILL ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
137 N RIDGE ST	Plastic	Repair/Replace Record	Yes	No	Copper	SL Repair/Replace Record	Yes
128 S HIGHLAND ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
264 S OAKWOOD BLVD	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
140 E RUBICON ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
322 E RUBICON ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
300 N LAKE ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
306 S MILL ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
113 N LAKE ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
70 ISLAND VIEW CIRCLE	Plastic	Previous Evaluation	Yes	No	Plastic	Previous Evaluation	Yes
55 ISLAND VIEW CIRCLE	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
630 W JUNEAU ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
804 CIRCLE DR	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
303 E ANTHONY ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
35 ISLAND VIEW CIRCLE	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
254 S MILL ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
203 N LAKE ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
318 S ANN ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
125 N LAKE ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
139 N Lake St.	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
139 N Lake St. Apt. C	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
204 E RUBICON ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
259 S ANN ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
253 S OAKWOOD BLVD	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
101 E TWEEDY ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
103 E TWEEDY ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
206 N LAKE ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
459 W JUNEAU ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes

474 SANDY LN WEST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
756 SPRUCE ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
222 W TWEEDY ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
240 S LAKE ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
773 SPRUCE ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
219 W JUNEAU ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
408 E RUBICON ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
32 -134 N HIGHLAND ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
134 N RIDGE ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
790 Circle Drive	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
217 S HUSTIS ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
251 S ANN ST	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
15 ISLAND VIEW CIRCLE	Copper	Previous Evaluation	NO	No	Copper	Previous Evaluation	Yes
75 ISLAND VIEW CIRCLE	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
27 ISLAND VIEW CIRCLE	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
685 Spruce St	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
550 ISLAND VIEW	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
227 W Tweedy St	Copper	Previous Evaluation	Yes	No	Copper	Installation Record	Yes
537 Juneau St F	Plastic	Repair/Replace Record	Yes	No	Plastic	Previous Evaluation	Yes
134 Lake St	Copper	Repair/Replace Record	Yes	No	Copper	Previous Evaluation	Yes
4410 Lakeview Rd	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
827 Lakeview Rd	Plastic	Previous Evaluation	Yes	No	Plastic	Previous Evaluation	Yes
200 Oakwood	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
237 Mill St	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
205 S Ridge	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
430 Sandy Ln	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
138 Oakwood Blvd	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
338 S Hustis St	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
127 N Ridge St	Plastic	Repair/Replace Record	Yes	No	Copper	SL Repair/Replace Record	Yes
410 Sandy Lane	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
249 S Hustis St	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
537 Juneau st apt D	Plastic	Previous Evaluation	Yes	No	Plastic	Previous Evaluation	Yes
785 Spruce St	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
312 S Hustis St.	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
224 Oakwood Blvd	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
325 W Tweedy St	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
225 N Highland	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
315 S Mill St.	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
122 E Tweedy St	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
439 W Juneau St	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
326 E Anthony St	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
321 S Wales St.	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
213 S Ann St.	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
236 S Ridge St.	Plastic	Installation Record	Yes	No	Copper	Previous Evaluation	Yes
320 E Rubicon St.	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
W4438 Lakeview Rd	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
418 W Griffith St.	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
108 N Daley Rd	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
208 S Hustis St	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
247 N Highland St.	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
412 E Griffith	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
221 N Highland St	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
218 E Rubicon St	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
156 Oakwood Blvd	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
111 S Lake St	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
131 S Ann st	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
422 south lake	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
328 E Griffith Lower	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
328 E Griffith Upper	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
N4262 N Daley Rd	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
434 E Griffith St.	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
416 E Rubicon St	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
220 N Ridge St	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
405 E Tweedy St.	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
253 S Lake St	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
207 W Tweedy	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
213 W Tweedy st	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
346 S Hustis St	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
763 W Juneau	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
512 S Lake st	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
123 E Tweedy	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
475 W Juneau St.	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
319 S Ann St	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes

323-325 S Lake St	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
302 S Wales St	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
117 N lake st	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
117 N lake st b upper	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
221 N Lake St	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
326 E Rubicon St	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
140 N Ridge	Plastic	Previous Evaluation	Yes	No	Copper	SL Repair/Replace Record	Yes
228 S Ridge St.	Plastic	Repair/Replace Record	Yes	No	Copper	SL Repair/Replace Record	Yes
222-224 S Wales	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
236 N Lake St Upper	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
234 N Lake St Lower	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
427 W Juneau	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
744 Spruce St	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
797 Circle Dr	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
121 N Lake St	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
127 E Tweedy St	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
127 S Ridge St.	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
126 W Juneau St Lower	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
126 W Juneau St Upper	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
228 W Juneau St	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
126 E Griffith St	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
123 S Lake St.	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
226 N Lake St.	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
126 W Griffith St	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
114 N Lake St.	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
204 E Griffith St.	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
221 E Anthony St.	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
249 S Mill St.	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
236 S wales St.	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
440 Sandy LN	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
257 S Lake St	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
717 Spruce St.	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
250 N Lake St.	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
784 Circle Dr	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
210 E Anthony St.	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
135 S Highland St.	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
152 Lakeview Rd	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
780 Spruce St	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
523 Island View Circle	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
4428 E Lakeview Rd	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
132 S Ridge	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
799 Spruce St.	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
253 N Ridge St.	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
125 Oakwood Blvd	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
332 W Tweedy St.	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
306 S Hustis St.	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
266 S Mill St.	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
266 S Ann St.	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
266 S Ann St.	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
229 N Lake St.	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
122 N Hustis St.	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
415 W Juneau St.	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
216 Oakwood BLVD	Copper	Previous Evaluation	Yes	No	Copper	Previous Evaluation	Yes
00 Industrial Drive WWTF	Plastic	Repair/Replace Record	Yes	No	Copper	SL Repair/Replace Record	Yes
500 Industrial Drive/Shop	Plastic	Repair/Replace Record	Yes	No	Copper	SL Repair/Replace Record	Yes
500 Industrial Drive/Ferris	Plastic	Repair/Replace Record	Yes	No	Plastic	SL Repair/Replace Record	Yes